

Errata Sheet
for
Advisory Circular 150/5370-10B
Standards for Specifying Construction of Airports

Last Update: June 12, 2006

This errata sheet logs content errors that were identified after the advisory circular (AC) was issued on 4/25/05. We will correct these errors when we issue the next change to the AC. All page numbers refer to the PDF version of the document posted on www.faa.gov.

| # | Description of Correction | Location | Rationale | Date Error was Published |
|---|--|-----------------------|---|--------------------------|
| 1 | The gradation requirements for Item P-209, CRUSHED AGGREGATE BASE COURSE, are incorrect. In Table 1, for sieve size No. 200, the percentage passing should be 0-8 not 0-5. | Page P-209-2, Table 1 | The percentage passing the No. 200 sieve was meant to remain unchanged from the percentage issued in AC 150/5370-10A. | 6/12/2006 |